

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/29/2025

Submitted Date:

01/29/2025

Document Number:

713301611

**FIELD INSPECTION FORM**

Loc ID 318265 Inspector Name: Kester, Michael On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
 Name of Operator: KP KAUFFMAN COMPANY INC  
 Address: 1700 LINCOLN ST STE 4550  
 City: DENVER State: CO Zip: 80203

**Findings:**

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	<a href="#">all inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241005	WELL	SI	04/01/2023	GW	123-08793	UPRR 43 PAN AM H 9	SI

**General Comment:**

[well site follow up inspection](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Sign not posted or information inaccurate at well

Corrective Action: Install sign to comply with Rule 605.d.

Date: 08/22/2024

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	<span style="color: blue;">safety guards</span>		
Corrective Action:		Date:	

**Equipment:**

					corrective date
Type: Bradenhead	# 1				
Comment:	<span style="color: blue;">piped to surface</span>				
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:					
Corrective Action:				Date:	
Type: Prime Mover	# 1				
Comment:	<span style="color: blue;">electric</span>				
Corrective Action:				Date:	
Type: Ancillary equipment	# 3				
Comment:	<span style="color: blue;">automation/electric panels</span>				
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
------	--	--	--

Comment:		
Corrective Action:	Date:	

**Inspected Facilities**

Facility ID: 241005 Type: WELL API Number: 123-08793 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Valves appeared to be closed at time of inspection

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 07/08/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 9 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<a href="#">Audit of scout card and related documents</a>	kestern	01/29/2025
<a href="#">Follow up inspection, doc 699506144, 8-8-2024, corrective actions appear to have NOT been completed.</a>		
<a href="#">This inspection does not nullify any orders or NOAV from the ECMC</a>		

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404074749	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6897527">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6897527</a>
713301612	site pic	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6897524">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6897524</a>