

Inspection/Audit Photos
Location: QB ENERGY CHEVRON/O33 596 PAD
Location ID: 335872
Date: 01/30/2025



Photo # 3910 Entrance to location

Photo # 3934 Location

Inspection/Audit Photos
Location: QB ENERGY CHEVRON/O33 596 PAD
Location ID: 335872
Date: 01/30/2025



Photo # 3911 Location



Photo # 3917 Location

Inspection/Audit Photos
Location: QB ENERGY CHEVRON/O33 596 PAD
Location ID: 335872
Date: 01/30/2025



Jan 30, 2025 at 2:10:05 PM
+39.565726,-108.171936 ±7.72m



Jan 30, 2025 at 2:24:58 PM
+39.565691,-108.171929 ±6.44m

Photo # 3919 Location

Photo # 3931 Location

Inspection/Audit Photos
Location: QB ENERGY CHEVRON/O33 596 PAD
Location ID: 335872
Date: 01/30/2025



Photo # 3949 SW corner of location



Photo # 3950 SE corner of location

Inspection/Audit Photos
Location: QB ENERGY CHEVRON/O33 596 PAD
Location ID: 335872
Date: 01/30/2025



Photo # 3951 NE corner of location



Photo # 3952 NW corner of location

Inspection/Audit Photos
Location: QB ENERGY CHEVRON/O33 596 PAD
Location ID: 335872
Date: 01/30/2025



Photo # 3924 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 3927 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos
Location: QB ENERGY CHEVRON/O33 596 PAD
Location ID: 335872
Date: 01/30/2025



Photo # 3943 PRV vent line does not comply with CECMC pressure safety device rules

Photo # 3944 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos
Location: QB ENERGY CHEVRON/O33 596 PAD
Location ID: 335872
Date: 01/30/2025



Photo # 3945 PRV vent line does not comply with CECMC pressure safety device rules

Photo # 3959 Unmarked deadman

Inspection/Audit Photos

Location: QB ENERGY CHEVRON/O33 596 PAD

Location ID: 335872

Date: 01/30/2025



Photo # 3690 Unmarked deadman