

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/28/2025

Submitted Date:

01/30/2025

Document Number:

708303372**FIELD INSPECTION FORM**Loc ID 335118 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Smelser, Wayne		wayne.smelser@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260917	WELL	PR	03/01/2011	GW	045-07921	PORTER FEDERAL 16-29	PR
260919	WELL	PR	12/10/2008	GW	045-07923	PORTER FEDERAL 9-29	PR
285049	WELL	PR	11/06/2007	GW	045-12359	SHIDELER FEDERAL 44B-29-692	PR
285050	WELL	PR	11/03/2007	GW	045-12360	SHIDELER FEDERAL 43D-29-692	PR
285051	WELL	PR	11/04/2007	GW	045-12361	SHIDELER FEDERAL 43A-29-692	PR
291190	WELL	PR	12/09/2014	GW	045-14317	SHIDELER FEDERAL 44A-29-692	PR

General Comment:**CECMC Inspection Report Summary**

On 1/28/2025 at approximately 13:35, Compliance Inspector Matthew Morris conducted an on-site audit at TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/29SESE at Location ID #335118 in Garfield County, Colorado.

During the audit, the following compliance issues were observed:

- 1) Illegible tank label on condensate tank
- 2) Stored supplies in tank containment. Open-ended hose poses a wildlife entry hazard.
- 3) Stained soil near separators
- 4) Stormwater; refer to Stormwater section

A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Illegible tank label on condensate tank.		
Corrective Action:	Install label to comply with Rule 605.h.	Date:	03/01/2025
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970)285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil near separators.		
Corrective Action:	Clean affected area and properly dispose of oily waste.	Date:	01/27/2023
Type	STORAGE OF SUPL		
Comment:	Stored supplies (load hose) in tank containment. Hose is open-ended and poses a wildlife entry hazard.		
Corrective Action:	Remove stored supplies from location.	Date:	02/04/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 6		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	HEATED STEEL AST		,	
Comment:	Staining present on tank walls/insulation.					
Corrective Action:					Date:	

Paint

Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Morris, Matthew

Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	HEATED STEEL AST		,
Comment:	Staining present on tank walls.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 260917 Type: WELL API Number: 045-07921 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 260919 Type: WELL API Number: 045-07923 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 285049 Type: WELL API Number: 045-12359 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 285050 Type: WELL API Number: 045-12360 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 285051 Type: WELL API Number: 045-12361 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291190 Type: WELL API Number: 045-14317 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		
		Gravel				
Berms						
Gravel						
Compaction						
Other	Fail					Insufficient erosion control
		Culverts				
Waddles	Fail					BMP needs maintenance
		Ditches				
		Check Dams				
		Compaction				

Comment: Insufficient erosion control of cutslope east of ECD. Rill erosion is undercutting waddle BMP and transporting sediment onto location.

Unable to inspect all Stormwater BMPs due to snow cover.

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 02/14/2025

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404076419	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6899339
708303373	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6899334