

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2025

Submitted Date:

01/30/2025

Document Number:

714202078**FIELD INSPECTION FORM**Loc ID 330725 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                                                 | Comment                         |
|--------------|-------|-------------------------------------------------------|---------------------------------|
| ,            |       | rbucogccinspectionreports@c<br>hevron.onmicrosoft.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 251713      | WELL | TA     | 06/01/2018  | GW         | 123-19516 | HSR-MOSER 15-27 | TA          |

**General Comment:**[This is an audit of HSR-MOSER 15-27 scout card and related documents followed by a field inspection.](#)

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | BATTERY              |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |                                                                              |       |            |
|--------------------|------------------------------------------------------------------------------|-------|------------|
| <b>Fencing/:</b>   |                                                                              |       |            |
| Type               | SEPARATOR                                                                    |       |            |
| Comment:           | wire                                                                         |       |            |
| Corrective Action: |                                                                              | Date: |            |
| Type               | WELLHEAD                                                                     |       |            |
| Comment:           | fencing surrounding wellhead appears to be in disrepair. See attached photo. |       |            |
| Corrective Action: | Comply with Rule 603.h.                                                      | Date: | 02/13/2025 |
| Type               | TANK BATTERY                                                                 |       |            |
| Comment:           | wire                                                                         |       |            |
| Corrective Action: |                                                                              | Date: |            |

|                                   |     |       |                 |
|-----------------------------------|-----|-------|-----------------|
| <b>Equipment:</b>                 |     |       | corrective date |
| Type: Horizontal Heated Separator | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Emission Control Device     | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Bird Protectors             | # 2 |       |                 |

|                     |     |       |  |
|---------------------|-----|-------|--|
| Comment:            |     | Date: |  |
| Corrective Action:  |     | Date: |  |
| Type: Plunger Lift  | # 1 |       |  |
| Comment:            |     | Date: |  |
| Corrective Action:  |     | Date: |  |
| Type: Gas Meter Run | # 1 |       |  |
| Comment:            |     | Date: |  |
| Corrective Action:  |     | Date: |  |
| Type: Bradenhead    | # 1 |       |  |
| Comment:            |     | Date: |  |
| Corrective Action:  |     | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL          | 1 | 300 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity                                                                       | Permeability (Wall) | Permeability (Base) | Maintenance      |
|--------------------|--------------------------------------------------------------------------------|---------------------|---------------------|------------------|
| Earth              | Adequate                                                                       | Walls Insufficient  | Base Sufficient     | Inadequate       |
| Comment:           | It appears to be multiple holes and damage to earth berm. See attached photos. |                     |                     |                  |
| Corrective Action: | Comply with Rule 603.o.                                                        |                     |                     | Date: 02/13/2025 |

| Contents           | # | Capacity | Type        | Tank ID | SE GPS |
|--------------------|---|----------|-------------|---------|--------|
| PRODUCED WATER     | 1 | OTHER    | BV CONCRETE |         | ,      |
| Comment:           |   |          |             |         |        |
| Corrective Action: |   |          |             |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 53 BBLs  |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity                             | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
|                    |                                      |                     |                     |             |
| Comment:           | Shares containment with other tanks. |                     |                     |             |
| Corrective Action: |                                      |                     |                     | Date:       |





**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 | Gravel                  |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

| Comment                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | User     | Date       |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------|
| <p>ECMC Inspection Report Summary</p> <p>WEATHER CONDITIONS: sunny, mud</p> <p>On Thursday, January 30, 2025 at approximately 1200, I, Inspector Brittani Santistevan, conducted an on-site inspection at HSR-MOSER 15-27 (Noble Energy, Inc), at location ID: 330725 in WELD COUNTY, Colorado.</p> <p>While there, I observed a shut-in facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"> <li>1. It appears the fencing surrounding the wellhead is in disrepair. Repair to comply with Rule 603.h. (Corrective Action Date: February 13, 2025) See attached photo #3, 4.</li> <li>2. It appears to be multiple holes and damage to earthen berm surround the crude and h2o tanks. Repair berm to comply with Rule 603.o. (Corrective Action Date: February 13, 2025) See attached photo #7-10.</li> </ol> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | santistb | 01/30/2025 |

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL                                                                                                                                                                     |
|--------------|----------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 404076359    | INSPECTION SUBMITTED | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6899097">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6899097</a> |
| 714202079    | Photos               | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6899078">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6899078</a> |