

Inspection/Audit Photos

Location: VISION ENERGY LLC USA-67S99W/28SEW (USA 1-28DF)

Location ID: 322450

Date: 02/3/2025



Photo # 3998 Entrance to location



Photo # 4012 Location

Inspection/Audit Photos

Location: VISION ENERGY LLC USA-67S99W/28SEW (USA 1-28DF)

Location ID: 322450

Date: 02/3/2025



Photo # 4014 Location



Photo # 4016 Location

Inspection/Audit Photos

Location: VISION ENERGY LLC USA-67S99W/28SEW (USA 1-28DF)

Location ID: 322450

Date: 02/3/2025



Photo # 4000 Equipment on location is not in compliance with CECMC reclamation rules



Photo # 4008 Equipment on location is not in compliance with CECMC reclamation rules

Inspection/Audit Photos

Location: VISION ENERGY LLC USA-67S99W/28SEW (USA 1-28DF)

Location ID: 322450

Date: 02/3/2025



Photo # 4010 Equipment on location is not in compliance with CECMC reclamation rules



Photo # 4024 Debris