

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/03/2025

Submitted Date:

02/06/2025

Document Number:

713400682

FIELD INSPECTION FORM

Loc ID: 322423 Inspector Name: Popejoy, Dusty On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10770
Name of Operator: VISION ENERGY LLC
Address: P O BOX 370
City: IGNACIO State: CO Zip: 81137

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-------------------|-------|----------------------------------|---------|
| ENERGY, VISION | | mollieo@maralexinc.com | |
| ENERGY, VISION | | mrine20@maralexinc.com | |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| Toews, Wesley | | wtoews@blm.gov | |
| Trujillo, Aaron | | aaron.trujillo@state.co.us | |
| ENERGY, VISION | | pbechtolt@maralexinc.com | |
| Haverkamp, Curtis | | curtis.haverkamp@state.co.us | |
| , DNR | | dnr_cogccengineering@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 210462 | WELL | SI | 07/06/2021 | GW | 045-06218 | DRY FORK FEDERAL 1-29 | PA |

General Comment:

[CECMC Inspection/Audit Report Summary](#)

On 2/3/2025 at approximately 12:00 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at VISION ENERGY LLC DRY FORK FEDERAL-67S99W/29SWNE (DRY FORK FEDERAL 1-29) at Location ID #322423 in Garfield County, Colorado.

Please refer to document numbers 402709206 & 402778831 appears the well has been P&A.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection/audit, the following compliance issues were observed:

1. Equipment - Equipment on location is not in compliance with CECMC reclamation rules with a CA of 03/6/2025

A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Access | | |
| Corrective ActionL | | Date: | |

Overall Good:

| | |
|----------------------------------|------------------------------------------|
| Emergency Contact Number: | |
| Comment: | <input style="width: 80%;" type="text"/> |
| Corrective Action: | <input style="width: 80%;" type="text"/> |
| | Date: _____ |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | |
|--------------------|------------------------------------------------------------------------------------------|-------------------------|
| Equipment: | | corrective date |
| Type: Other | # 2 | |
| Comment: | Equipment on location is not in compliance with CECMC reclamation rules, refer to photos | |
| Corrective Action: | Comply with CECMC reclamation rules | Date: <u>03/06/2025</u> |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 210462 Type: WELL API Number: 045-06218 Status: SI Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Please refer to document numbers 402709206 & 402778831 appears the well has been P&A. Unable to locate FORM 6 Subsequent Report of Abandonment.

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|------------------|
| | | Ditches | | | | |
| | | Compaction | | | | Light compaction |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|----------------------------------------------------------------------------------------|----------|------------|
| Please refer to Equipment for corrective action and Inspected Facilities for comments. | popejoyd | 02/05/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 713400683 | Inspection-Audit Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6908117 |