

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/29/2025

Submitted Date:

01/31/2025

Document Number:

701104136

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
LONGWORTH, MIKE 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 17180

Name of Operator: CITATION OIL & GAS CORP

Address: 14077 CUTTEN RD

City: HOUSTON State: TX Zip: 77069

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wheeler, Steven		steven.wheeler@state.co.us	
Sanchez, Chris		chris.sanchez@state.co.us	
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	
Quint, Craig		craig.quint@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
255968	GAS PROCESSING PLANT	AC	03/02/2005		-	MPU Press Maint and Inject Facility	AC

General Comment:

Flowline Integrity Inspection

Lube oil berm floor is saturated oil. Stained ground around equipment and buried line.

Lube tank missing some of the required information per Rule 605.h.2

Capacity, operator name and number,

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Lube tank missing some of the required information per Rule 605.h.2 Capacity, operator name and number,		
Corrective Action:	Install sign to comply with Rule 605.h.2	Date:	03/07/2025

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
Lube Oil	Tank			
Comment:	Lube oil berm floor is saturated oil. Stained ground around equipment and buried line.			
Corrective Action:	In accordance with Rule 912.a.(2) Operator will investigate, cleanup, and document impacts resulting from Spill and Releases as soon as the impacts are discovered. Contact the area Environmental Protection Specialist Chris Sanchez			Date: 02/04/2025

In Containment: No

Comment: ☒ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
LUBE OIL	1		STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				Inadequate
Comment:	Berm floor is saturated oil.			
Corrective Action:	Maintain berm			Date: 03/07/2025

Venting:

Yes/No		
Comment:		
Corrective Action:		Date: _____

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities

Facility ID: 255968 Type: GAS API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404077898	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6900759
701104137	Flowline integrity inspection 701104136 photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6900756