

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/30/2025

Submitted Date:

01/31/2025

Document Number:

715201637

**FIELD INSPECTION FORM**

Loc ID 321892 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 83130  
Name of Operator: STRACHAN EXPLORATION INC  
Address: 992 S 4TH AVE SUITE 100-461  
City: BRIGHTON State: CO Zip: 80601

**Findings:**

- 15 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Harms, Jason		Jason@strachanexploration.com	
Reed, Shawn	303-562-6530	shawn@sreedconsulting.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208414	WELL	PR	06/01/2020	OW	017-07349	UPRC 1-35	PR

**General Comment:**

[SE Compliance Specialist Brian Welsh](#) conducted a routine field inspection of the well location and equipment

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Partially elevated gravel road along farm ground with a cattle guard		
Corrective Action	L		Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign mounted to fence at unit. Update to current operator		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 03/02/2025
Type	TANK LABELS/PLACARDS		
Comment:	Install tank labels		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 03/02/2025
Type	BATTERY		
Comment:	Lease sign at tanks needs updated to current operator		
Corrective Action:	Install sign to comply with Rule 605.a.		Date: 03/02/2025

<b>Emergency Contact Number:</b>		
Comment:	<input style="width: 100%;" type="text"/>	
Corrective Action:	<input style="width: 100%;" type="text"/>	
		Date: _____

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Wire panels around tank battery		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Wire panels around wellhead and unit		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	CMI 320		
Corrective Action:			Date:

Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: FWKO	# 1		
Comment:	FWKO west side of tank battery		
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	Control panel, cathodic rectifier, electric panel, chemical tank w/containment		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	200 BBLs	FIBERGLASS AST		38.879550,-102.300150
Comment:	Water tank on west side of gun barrel tank has been removed				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0	400 BBLs	FIBERGLASS AST		38.879550,-102.300150
Comment:	Gun barrel on west side of production tanks has been removed				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	500 BBLs	FIBERGLASS AST		38.879550,-102.300150

Comment:	Overflow for production water tank on west side of tank battery has been removed	
Corrective Action:		Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				Date:
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	FIBERGLASS AST		38.879550,-102.300150
Comment:					Date:
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				Date:
Corrective Action:				Date:

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 208414 Type: WELL API Number: 017-07349 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Tank battery is 350' south of wellhead](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404077213	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6900238">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6900238</a>
715201638	Puming unit	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6900200">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6900200</a>
715201639	tank battery	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6900201">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6900201</a>