

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/27/2025

Submitted Date:

02/06/2025

Document Number:

701104140

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Findings:

- 4 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Quint, Craig		craig.quint@state.co.us	
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	
Wheeler, Steven		steven.wheeler@state.co.us	
Sanchez, Chris		chris.sanchez@state.co.us	
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488536	SPILL OR RELEASE	AC	11/21/2024		-	Speaker Unit Compressor	AC

General Comment:

Flowline Integrity Inspection
Stained ground around crude oil tank.
No berm or secondary containment around tank.
100 bbl tank has 2 labels on it. One is Crude oil and the other is Produced water.
Company name and phone number is missing on tank.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	100 bbl tank has 2 labels on it. One is Crude oil and the other is Produced water. Company name and phone number is missing on tank.		
Corrective Action:	Install sign to comply with Rule 605.h.2	Date:	03/07/2025

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume			
Lube Oil	Tank				
Comment:	Stained ground around Crude oil tank. Stained ground at containers at south west corner on compressor building.				
Corrective Action:	In accordance with Rule 912.a.(2) Operator will investigate, cleanup, and document impacts resulting from Spill and Releases as soon as the impacts are discovered. Contact the area Environmental Protection Specialist Chris Sanchez			Date:	02/10/2025

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	100 BBLs	FIBERGLASS AST			
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>

Paint

Condition	Inadequate		
Other (Content)	<input type="text"/>		
Other (Capacity)	<input type="text"/>		
Other (Type)	<input type="text"/>		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	No berm or secondary containment around tank. Stained ground around tank.				
Corrective Action:	Install berm around lube oil tank.			Date:	03/07/2025

Venting:

Yes/No	<input type="text"/>			
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>		Date:	<input type="text"/>

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 488536 Type: SPILL OR API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104142	Flowline integrity inspection 701104140 photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6909770