

Inspection/Audit Photos
Location Name: QB Energy GMU 23-14 (C26NW) Pad
Location #: 335163



Feb 3, 2025 at 11:59:12 AM
CO



Feb 3, 2025 at 11:59:22 AM
CO

Photo # 3080 From entrance to location

Photo # 3081 From entrance to location

Inspection/Audit Photos

Location Name: QB Energy GMU 23-14 (C26NW) Pad
Location #: 335163




Photo # 3082 Location

Photo # 3083 Location

Inspection/Audit Photos
Location Name: QB Energy GMU 23-14 (C26NW) Pad
Location #: 335163



Photo # 3084 Location



Photo # 3085 Location

Inspection/Audit Photos
Location Name: QB Energy GMU 23-14 (C26NW) Pad
Location #: 335163



Photo # 3086 Location



Photo # 3087 Location

Inspection/Audit Photos
Location Name: QB Energy GMU 23-14 (C26NW) Pad
Location #: 335163



Photo # 3088 Location



Photo # 3089 Location

Inspection/Audit Photos
Location Name: QB Energy GMU 23-14 (C26NW) Pad
Location #: 335163



Photo # 3090 Location

Photo # 3091 Location

Inspection/Audit Photos
Location Name: QB Energy GMU 23-14 (C26NW) Pad
Location #: 335163



Feb 3, 2025 at 12:34:12 PM
CO



Feb 3, 2025 at 12:32:11 PM
CO

Photo # 3092 Location

Photo # 3093 Location

Inspection/Audit Photos
Location Name: QB Energy GMU 23-14 (C26NW) Pad
Location #: 335163



Photo # 7693 From inspection 708905468 conducted on 01/09/2025 PRV vent line does not comply with CECMC pressure safety device rules

Photo # 3094 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos
Location Name: QB Energy GMU 23-14 (C26NW) Pad
Location #: 335163



Photo # 3095 Staining in secondary containment



Photo # 3096 Staining in secondary containment