

Inspection Photos
Location Name: Eyestone 3-35
API Number: 125-07469



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Eyestone 3-35
API Number: 125-07469



3. View of broken power panel post and panel.



4. View of check valve with missing cap.

Inspection Photos
Location Name: Eyestone 3-35
API Number: 125-07469



5. View of leaking check valve as spill release point.



6. Well location overview.

Inspection Photos
Location Name: Eyestone 3-35
API Number: 125-07469



7. Lease sign at gathering location.



8. Gas meter inside meter shed.

Inspection Photos
Location Name: Eyestone 3-35
API Number: 125-07469



9. View of roof damage on meter shed.



10. Gathering location overview.