

Inspection/Audit Photos
Location Name: QB Energy HILL 16-5B1 (E16) Pad
Location #: 334915



Feb 10, 2025 at 12:26:34 PM
CO



Feb 10, 2025 at 12:32:48 PM
CO

Photo # 4632 From entrance to location

Photo # 4633 Location

Inspection/Audit Photos
Location Name: QB Energy HILL 16-5B1 (E16) Pad
Location #: 334915



Photo # 4634 Location



Photo # 4635 Location

Inspection/Audit Photos
Location Name: QB Energy HILL 16-5B1 (E16) Pad
Location #: 334915



Photo # 4636 Location

Photo # 4637 Location

Inspection/Audit Photos
Location Name: QB Energy HILL 16-5B1 (E16) Pad
Location #: 334915



Photo # 4638 Location



Photo # 4639 Location

Inspection/Audit Photos
Location Name: QB Energy HILL 16-5B1 (E16) Pad
Location #: 334915



Photo # 4640 Flowline heating insulation open ended/wildlife hazard/available for entry by wildlife



Photo # 4641 Valves used for annular pressure monitoring buried & not exposed/not in compliance with CECMC rules (HILL 16-4A1 well)

Inspection/Audit Photos
Location Name: QB Energy HILL 16-5B1 (E16) Pad
Location #: 334915



Photo # 4642 Hole in liner/liner needs maintenance



Photo # 4643 Hole in liner/liner needs maintenance

Inspection/Audit Photos
Location Name: QB Energy HILL 16-5B1 (E16) Pad
Location #: 334915



Photo # 4644 Hole in liner/liner needs maintenance



Photo # 4645 Hole in liner/liner needs maintenance

Inspection/Audit Photos
Location Name: QB Energy HILL 16-5B1 (E16) Pad
Location #: 334915




Photo # 4646 Tank label contains inaccurate information