

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/30/2025

Submitted Date:

02/04/2025

Document Number:

708303398

**FIELD INSPECTION FORM**

Loc ID 324038 Inspector Name: Morris, Matthew On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name   | Phone | Email                              | Comment |
|----------------|-------|------------------------------------|---------|
| Popejoy, Dusty |       | dusty.popejoy@state.co.us          |         |
| , TEP          |       | COGCCInspectionReports@terraep.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 211548      | WELL | PR     | 11/16/1998  | GW         | 045-07308 | UNOCAL GM 231-34 | PR          |

**General Comment:**

[CECMC Inspection Report Summary](#)

On 1/30/2025 at approximately 16:10, Compliance Inspector Matthew Morris conducted an on-site audit at TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/34SWSW at Location ID #324038 in Garfield County, Colorado.

During the audit, the following compliance issues were observed:

- 1) Weathered and illegible battery sign

A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

Overall Good:

**Signs/Marker:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | WELLHEAD   |       |            |
| Comment:           |  |       |            |
| Corrective Action: |  | Date: |            |
| Type               | OTHER  |       |            |
| Comment:           | Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank. |       |            |
| Corrective Action: |  | Date: |            |
| Type               | TANK LABELS/PLACARDS   |       |            |
| Comment:           |  |       |            |
| Corrective Action: |  | Date: |            |
| Type               | BATTERY  |       |            |
| Comment:           | Weathered and illegible battery sign.  |       |            |
| Corrective Action: | Install sign to comply with Rule 605.e.  | Date: | 03/07/2025 |

**Emergency Contact Number:**

Comment:

Corrective Action:

Date:

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |              |       |  |
|--------------------|--------------|-------|--|
| Type               | SEPARATOR    |       |  |
| Comment:           | Hog panels   |       |  |
| Corrective Action: |              | Date: |  |
| Type               | WELLHEAD     |       |  |
| Comment:           | Pipe rails   |       |  |
| Corrective Action: |              | Date: |  |
| Type               | TANK BATTERY |       |  |
| Comment:           | Hog panels   |       |  |
| Corrective Action: |              | Date: |  |

**Equipment:**

|                    |     |       |                 |
|--------------------|-----|-------|-----------------|
| Type: Dehydrator   | # 1 |       | corrective date |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |

|                                   |     |  |       |
|-----------------------------------|-----|--|-------|
| Type: Plunger Lift                | # 1 |  |       |
| Comment:                          |     |  |       |
| Corrective Action:                |     |  | Date: |
| Type: Bird Protectors             | # 2 |  |       |
| Comment:                          |     |  |       |
| Corrective Action:                |     |  | Date: |
| Type: Horizontal Heated Separator | # 1 |  |       |
| Comment:                          |     |  |       |
| Corrective Action:                |     |  | Date: |
| Type: Bradenhead                  | # 1 |  |       |
| Comment:                          |     |  |       |
| Corrective Action:                |     |  | Date: |
| Type: Gas Meter Run               | # 1 |  |       |
| Comment:                          |     |  |       |
| Corrective Action:                |     |  | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity  | Type      | Tank ID | SE GPS |
|--------------------|---|-----------|-----------|---------|--------|
| PRODUCED WATER     | 1 | <100 BBLS | STEEL AST |         |        |
| Comment:           |   |           |           |         |        |
| Corrective Action: |   |           |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 80 bbls  |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
|                    |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    |       |
|                    |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: |       |
|                    | Date: |

**Inspected Facilities**

Facility ID: 211548 Type: WELL API Number: 045-07308 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Compaction              |                       |               |                          |         |
| Gravel           |                 |                         |                       |               |                          |         |
|                  |                 | Check Dams              |                       |               |                          |         |
| Compaction       |                 |                         |                       |               |                          |         |
|                  |                 | Culverts                |                       |               |                          |         |
|                  |                 | Sediment Traps          |                       |               |                          |         |
|                  |                 | Rip Rap                 |                       |               |                          |         |
| Berms            |                 |                         |                       |               |                          |         |
|                  |                 | Ditches                 |                       |               |                          |         |
|                  |                 | Gravel                  |                       |               |                          |         |

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 404081693    | INSPECTION SUBMITTED | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6905385">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6905385</a> |
| 708303399    | Photo Log            | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6905382">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6905382</a> |