

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/11/2025

Submitted Date:

02/11/2025

Document Number:

697010960

FIELD INSPECTION FORM

Loc ID 318592 Inspector Name: Peterson, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---------------------------------------------------|---------|
| | | rbucogccinspectionreports@chevron.onmicrosoft.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 241682 | WELL | TA | 09/01/2019 | GW | 123-09471 | Dinner Lois Unit 2 | TA |

General Comment:

This is a routine audit. Any corrective actions from previous audits that have not been addressed are still applicable. There were no operator personnel on location at the time of this field audit.

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|-------------------------------------------------|-------|------------|
| | Type WELLHEAD | | |
| Comment: | Sign is not posted at well, see attached photo. | | |
| Corrective Action: | Install sign to comply with Rule 605.d. | Date: | 04/15/2025 |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: Panel

Corrective Action: _____ Date: _____

Equipment:

corrective date

| | | | | | |
|---------------------|-----------------------------------------|--|--|-------|--|
| Type: Pig Station | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Type: Bradenhead | # 1 | | | | |
| Comment: | Bradenhead valve is exposed at surface. | | | | |
| Corrective Action: | | | | Date: | |
| Type: Gas Meter Run | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Venting:

Yes/No NO

Comment: _____

Corrective Action: _____ Date: _____

Flaring:

| | | | |
|--------------------|--|--|-------------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |

Inspected Facilities

Facility ID: 241682 Type: WELL API Number: 123-09471 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|------------|
| <p>ECMC Audit Report Summary On Tuesday 2/11/2025 at approximately 14:00 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Noble Energy Dinner Lois Unit #2 location #318592 in Weld County, Colorado. While there, I observed that the wellhead sign was not posted. During this inspection the following possible compliance issues were observed: Rule 605.d. with a corrective action date of 4/15/2025. A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p> | petersont | 02/11/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 697010961 | Photo | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6914374 |