

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC MV/11-11 PAD

Location ID: 334809

Date: 02/11/2025



Photo # 4664 Entrance to location



Photo # 4675 Location

Inspection/Audit Photos
Location: TEP ROCKY MOUNTAIN LLC MV/11-11 PAD
Location ID: 334809
Date: 02/11/2025



Photo # 4665 Location



Photo # 4672 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC MV/11-11 PAD

Location ID: 334809

Date: 02/11/2025



Feb 11, 2025 at 11:21:43 AM
+39.457039,-108.081370 ±5.27m
De Beque



Feb 11, 2025 at 11:46:14 AM
+39.456868,-108.081156 ±6.50m
De Beque

Photo # 4674 Location

Photo # 4690 SE corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC MV/11-11 PAD

Location ID: 334809

Date: 02/11/2025



Photo # 4691 SW corner of location



Photo # 4692 NW corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC MV/11-11 PAD

Location ID: 334809

Date: 02/11/2025



Photo # 4693 NE corner of location



Photo # 4682 Staining

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC MV/11-11 PAD

Location ID: 334809

Date: 02/11/2025



Photo # 4683 Staining



Photo # 4699 Staining

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC MV/11-11 PAD

Location ID: 334809

Date: 02/11/2025



Photo # 4701 Staining



Photo # 4703 Erosion & transport of sediment off location/insufficient BMP's

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC MV/11-11 PAD

Location ID: 334809

Date: 02/11/2025



Photo # 4708 Erosion & transport of sediment off location/insufficient BMP's



Photo # 4713 Subsidence on slope, additionally is a wildlife hazard

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC MV/11-11 PAD

Location ID: 334809

Date: 02/11/2025



Photo # 4759 Subsidence on slope, additionally is a wildlife hazard



Photo # 4679 Open ended load line