

# Inspection Photos

Loc: 484358

Operator: DESERT EAGLE OPERATING LLC

Inspection Date: 2/10/2025

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos




**Photo 1.** Facing east along the access road. This area of the road is rutted and needs to be repaired with BMP's.





## Inspection Photos



**Photo 2.** Facing east toward the wellsite and engine compressor.



## Inspection Photos



**Photo 3.** Facing east at the wellsite and engine compressor.





## Inspection Photos



**Photo 4.** Facing toward the engine compressor.





## Inspection Photos



**Photo 5.** Northeast corner facing west. Perimeter wattles have been reinstalled. Disturbed area have not establish perennial vegetation.





## Inspection Photos



**Photo 6.** Facing west toward the flowline disturbance.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:484358 | Date: 2/10/2025