

# Failure Report

## Verdad Resources

John Schrader

Heather Jaquez  
Chemical Account Manager  
505.793.7594  
heather.jaquez@halliburton.com

County Line Utility Line  
1/9/2025

---

### Details and Suspected Method of Failure

- Pipe from connecting line for west and east headers
- Batch treating older wells
- CO2 corrosion
- Line was stagnant for long period
  - Causing an acceleration metal loss

West Header



East Header

