

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/10/2025

Submitted Date:

02/13/2025

Document Number:

713400707**FIELD INSPECTION FORM**Loc ID 334183 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**27 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
ENERGY, QB		ecmc.inspections@qb-energy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
306	WELL	PR	03/02/2010	GW	045-15478	PRATHER/LATHAM 3-31A	PR
307	WELL	PR	04/14/2010	GW	045-15479	MANESS 3-31D	PR
308	WELL	PR	03/01/2010	GW	045-15480	MANESS 3-31B	PR
309	WELL	SI	02/01/2024	GW	045-15481	MANESS 3-31C	PR
310	WELL	PR	04/01/2010	GW	045-15482	PRATHER/LATHAM 3-21B	PR
311	WELL	PR	03/31/2010	GW	045-15483	MANESS 3-21C	PR
312	WELL	PR	04/13/2010	GW	045-15484	MANESS 3-21D	PR
313	WELL	PR	03/10/2010	GW	045-15485	PRATHER/LATHAM 3-21A	PR

General Comment:**CECMC Inspection/Audit Report Summary**

On 2/10/2025 at approximately 12:02 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at QB ENERGY PRATHER/LATHAM-68S96W/3NWN (SOUTH GRAND VALLEY PAD - 3 B) at Location ID #334183 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection/audit, the following compliance issues were observed:

1. Equipment - Open ended piping/wildlife hazard/available for entry by wildlife with a CA date of 02/19/2025
2. Signs/Marker - Signs at tank battery lack required information/do not comply with CECMC rules with a CA date of 03/13/2025

A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign near entrance to location		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Signs at tank battery lack required information/do not comply with CECMC, refer to photos		
Corrective Action:	Comply with CECMC Signage rules	Date:	03/13/2025
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	1 tank label showing signs of disrepair		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-866-580-9382/911

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Open ended piping/wildlife hazard/available for entry by wildlife, refer to photo		
Corrective Action:	Comply with CECMC wildlife rules	Date:	02/19/2025
Type: Plunger Lift	# 8		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:	No form of pressure monitoring equipment. Bradenhead valves are accessible		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	5	300 BBLS	STEEL AST		,	
Comment:	3 of 5 Tanks equipped with telemetry					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:	Centralized containment			
Corrective Action:			Date:	

Inspected Facilities				
Facility ID:	306	Type:	WELL	API Number: 045-15478
Status:	PR	Insp. Status:	PR	
Producing Well				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	307	Type:	WELL	API Number: 045-15479
Status:	PR	Insp. Status:	PR	
Producing Well				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	308	Type:	WELL	API Number: 045-15480
Status:	PR	Insp. Status:	PR	
Producing Well				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	309	Type:	WELL	API Number: 045-15481
Status:	SI	Insp. Status:	PR	
Producing Well				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	310	Type:	WELL	API Number: 045-15482
Status:	PR	Insp. Status:	PR	
Producing Well				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	311	Type:	WELL	API Number: 045-15483
Status:	PR	Insp. Status:	PR	
Producing Well				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	312	Type:	WELL	API Number: 045-15484
Status:	PR	Insp. Status:	PR	
Producing Well				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	313	Type:	WELL	API Number: 045-15485
Status:	PR	Insp. Status:	PR	
Producing Well				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Producing Well			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Berms				
Berms						
		Ditches				
Gravel						Sparse
		Culverts				
Sediment Traps						
		Gravel				Sparse
Ditches						

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Equipment & Signs/Marker for corrective actions and comments.	popejoyd	02/12/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400708	Inspection-Audit Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6916916