

**Inspection Photos**  
**Location Name: Pete Montoya 1**  
**Location ID: 311280**



**Photo 1 Location**



**Photo 2 Dead vegetation around Horizontal Heated separator.**

**Inspection Photos**  
**Location Name: Pete Montoya 1**  
**Location ID: 311280**



**Photo 3 Dead vegetation inside/outside tank battery fencing.**



**Photo 4 Dead vegetation around flow line manifold & around the tanks .**



Inspection Photos  
Location Name: Pete Montoya 1  
Location ID: 311280



Photo 5 Dead vegetation inside/outside tank battery fencing & berm.



Photo 6 Tank battery sign.

# Inspection Photos Location Name: Pete Montoya 1 Location ID: 311280



Photo 7 Tank battery, dead vegetation inside/outside tank battery fencing.



Photo 8 Wellhead sign.



Inspection Photos  
Location Name: Pete Montoya 1  
Location ID: 311280



Photo 9 Wellhead




Photo 10 Ancillary equipment.

Inspection Photos  
Location Name: Pete Montoya 1  
Location ID: 311280



Photo 11 Pump jack



Photo 12 Gas Meter run.

Inspection Photos  
Location Name: Pete Montoya 1  
Location ID: 311280




Photo 13 Card indicates that calibration is not current.

