

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/27/2025

Submitted Date:

02/06/2025

Document Number:

701104140

**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
LONGWORTH, MIKE 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 17180

Name of Operator: CITATION OIL &amp; GAS CORP

Address: 14077 CUTTEN RD

City: HOUSTON State: TX Zip: 77069

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wheeler, Steven		steven.wheeler@state.co.us	
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	
Sanchez, Chris		chris.sanchez@state.co.us	
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	
Quint, Craig		craig.quint@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488536	SPILL OR RELEASE	AC	11/21/2024		-	Speaker Unit Compressor	AC

**General Comment:**

Flowline Integrity Inspection  
 Stained ground around crude oil tank.  
 No berm or secondary containment around tank.  
 100 bbl tank has 2 labels on it. One is Crude oil and the other is Produced water.  
 Company name and phone number is missing on tank.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	100 bbl tank has 2 labels on it. One is Crude oil and the other is Produced water. Company name and phone number is missing on tank.		
Corrective Action:	Install sign to comply with Rule 605.h.2	Date:	03/07/2025

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Lube Oil	Tank			
Comment:	Stained ground around Crude oil tank. Stained ground at containers at south west corner on compressor building.			
Corrective Action:	In accordance with Rule 912.a.(2) Operator will investigate, cleanup, and document impacts resulting from Spill and Releases as soon as the impacts are discovered. Contact the area Environmental Protection Specialist Chris Sanchez			Date: 02/10/2025

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	100 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	No berm or secondary containment around tank. Stained ground around tank.			
Corrective Action:	Install berm around lube oil tank.			
			Date:	03/07/2025

**Venting:**

Yes/No			
Comment:			
Corrective Action:	Date:		

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 488536    Type: SPILL OR    API Number: -    Status: AC    Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404085986	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6909772">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6909772</a>
701104142	Flowline integrity inspection 701104140 photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6909770">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6909770</a>