

Inspection/Audit Photos
Location Name: QB Energy SHIDELER (G32NE) Pad
Location #: 334853



Feb 13, 2025 at 2:52:40 PM
CO



Feb 13, 2025 at 2:54:25 PM
CO

CAERUS Caerus Picance LLC
 South Piceance
 PAD G32NE
 SWNE SEC-32 6S R92W
 UNIT # COC56608A
 TANK # 81193, 82374, 81193

WELL NAME	API#	LAT	LONG
BENNETT 32-7	05045077010000	39.485491	-107.688637
SHIDELER 32-6	05045077020000	39.48558	-107.68865
SHIDELER 32-1	05045077030000	39.48564	-107.68866
SHIDELER 32-1	05045077010000	39.48553	-107.68864

ACCESSED BY- County Road 315
 IN CASE OF EMERGENCY DIAL
 970-285-2615 OR 911

CAERUS Caerus Picance LLC
 South Piceance
 PAD G32NEC
 SWNE SEC-32 6S R92W
 UNIT # COC56608A
 TANK # 82374, 81193

WELL NAME	API#	LAT	LONG
SHIDELER 32-8C	05045094460000	39.48645	-107.68845
SHIDELER 32-2D	05045094470000	39.48651	-107.68847

ACCESSED BY- County Road 315
 IN CASE OF EMERGENCY DIAL
 970-285-2615 OR 911

Photo # 6008 From entrance to location

Photo # 6009 Location

Inspection/Audit Photos
Location Name: QB Energy SHIDELER (G32NE) Pad
Location #: 334853



Photo # 6010 Location



Photo # 6011 Location

Inspection/Audit Photos
Location Name: QB Energy SHIDELER (G32NE) Pad
Location #: 334853



Feb 13, 2025 at 3:07:43 PM
CO



Feb 13, 2025 at 3:07:24 PM
CO

Photo # 6012 Location

Photo # 6013 Location

Inspection/Audit Photos
Location Name: QB Energy SHIDELER (G32NE) Pad
Location #: 334853



Photo # 6014 Location



Photo # 6015 Location

Inspection/Audit Photos
Location Name: QB Energy SHIDELER (G32NE) Pad
Location #: 334853



Photo # 6016 Unmarked deadman



Photo # 6017 Same unmarked deadman

Inspection/Audit Photos
Location Name: QB Energy SHIDELER (G32NE) Pad
Location #: 334853




Photo # 6018 Cal card




Photo # 6019 Meter not calibrated annually/not in compliance with CECMC rules

Inspection/Audit Photos
Location Name: QB Energy SHIDELER (G32NE) Pad
Location #: 334853



**Photo # 6020 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife**



**Photo # 6021 Flowline heating insulation damaged/wildlife
hazard/available for entry by wildlife**