

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/13/2025

Submitted Date:

02/14/2025

Document Number:

708905750**FIELD INSPECTION FORM**Loc ID 334853 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

26 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
QB Energy		ecmc.inspections@qb-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211312	WELL	SI	05/01/2024	GW	045-07071	BENNETT 32-7 (G32NE)	SI
259285	WELL	PR	06/01/2002	GW	045-07701	SHIDELER 32-1 (G32NE)	PR
259286	WELL	SI	05/01/2024	GW	045-07702	SHIDELER 32-6 (G32NE)	SI

**General Comment:****CECMC Inspection/Audit Report Summary**

On 02/13/2025 at approximately 14:52 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection/audit at QB Energy SHIDELER (G32NE) Pad.

Location # 334853 in Garfield County Colorado.

Location is within High Priority/Density/NSO/Black Bear Habitat areas.

Location is approximately 28 yards from Mamm Creek.

While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Equipment - BENNETT 32-7 meter not calibrated annually with a CA date of 03/16/2025
2. Equipment - Flowline heating insulation open ended/damaged/wildlife hazard with a CA date of 02/21/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection/audit report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Sign at intersection of Mamm Creek Road & start of lease road		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Signs at separator		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date	
Type: Bradenhead	# 3				
Comment:	Pressure transducers located on bradenheads, bradenhead valves are accessible.				
Corrective Action:					Date:
Type: Deadman # & Marked	# 1				
Comment:	1 unmarked deadman - please refer to photo log  All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.				
Corrective Action:					Date:
Type: Bird Protectors	# 3				
Comment:					
Corrective Action:					Date:
Type: Plunger Lift	# 1				
Comment:	SHIDELER 32-1 well on plunger lift  Remaining 2 wells not on plunger lift				
Corrective Action:					Date:
Type: Gas Meter Run	# 2				
Comment:					
Corrective Action:					Date:
Type: Other	# 2				
Comment:	Flowline heating insulation open ended/wildlife hazard/available for entry by wildlife  Flowline heating insulation damaged/wildlife hazard/available for entry by wildlife				
Corrective Action:	Comply with CECMC wildlife rules				Date: 02/21/2025
Type: Horizontal Heated Separator	# 3				
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run	# 1				
Comment:	BENNETT 32-7 meter not calibrated annually/not in compliance with CECMC rules				
Corrective Action:	Comply with CECMC meter calibration rules				Date: 03/16/2025
Type: Gas Meter Run	# 1				
Comment:	Summit Midstream				
Corrective Action:					Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment:	Centralized containment				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment:	Centralized containment				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	500 gal
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment:	Centralized containment				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLS	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:				Date:	

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment:	Centralized containment				
Corrective Action:					Date: <div></div>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date: <div></div>	

Flaring:

Type		
Comment:		
Corrective Action:		Date: <div></div>

Inspected Facilities									
Facility ID:	211312	Type:	WELL	API Number:	045-07071	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder:									
Comment: Shut In Last produced April 2024									
Corrective Action: Date:									
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	259285	Type:	WELL	API Number:	045-07701	Status:	PR	Insp. Status:	PR
Producing Well									
Comment: Producing, well on plunger lift									
Corrective Action: Date:									
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	259286	Type:	WELL	API Number:	045-07702	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder:									
Comment: Shut In Last produced April 2024									
Corrective Action: Date:									
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse to none
Gravel						Sparse to none in areas
Retention Ponds						
Berms						
		Compaction				
Compaction						Small amount of light compaction
Ditches						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Equipment for corrective actions	smelserw	02/14/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708905751	Inspection/Audit 708905750 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6920069">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6920069</a>
708905752	Inspection/Audit 708905750 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6920070">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6920070</a>