

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/17/2025

Submitted Date:

02/18/2025

Document Number:

717300224

FIELD INSPECTION FORM

Loc ID 321263 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206553	WELL	TA	06/01/2024	GW	013-06048	KANE 20-10	PA
460851	Location	AC			-	Kane #20-10	EG

General Comment:

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 206553 Type: WELL API Number: 013-06048 Status: TA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 460851 Type: Location API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well is plugged and abandoned (Kane 20-10); ECMC form 42 notice of start of plugging operations doc #403972553 received on 10/28/2024. The facility/ tank battery has been decommissioned; tanks, equipment and on location flowlines removed. No flowlines/ risers observed at PA well or facility/ battery areas. Remediation work is in progress. Note: an active midstream pipeline valve set/ pig station is located on the SW corner of location.	maclarej	02/18/2025
As outlined on ECMC form 19 spill report Doc #404093674 received on 02/13/2025: While conducting facility decommissioning activities at Extraction's Kane 20-10 tank battery, historical impacts were discovered. Lease operators are coached to conduct routine AVO inspections at all oil and gas locations.	maclarej	02/18/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300225	Signage	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6923553
717300226	Facility/ battery decommissioned; NO FL/ Risers	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6923554
717300227	PA well area; No FL/ Risers	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6923555