

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LOUTHAN 41B-34 Pad

Location ID: 335439



Photo # 6357 From entrance to location




Photo # 6358 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LOUTHAN 41B-34 Pad

Location ID: 335439



Photo # 6359 Location



Photo # 6360 Location



Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LOUTHAN 41B-34 Pad

Location ID: 335439



Photo # 6361 Location




Photo # 6362 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LOUTHAN 41B-34 Pad

Location ID: 335439



Photo # 6363 Location



Photo # 6364 Mechanical condition – possible wellhead leak on the LOUTHAN 31B-34 wellhead

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LOUTHAN 41B-34 Pad

Location ID: 335439



Photo # 6365 Mechanical condition – possible wellhead leak on the LOUTHAN 31B-34 wellhead



Photo # 6366 Mechanical condition – possible wellhead leak on the LOUTHAN 31B-34 wellhead

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LOUTHAN 41B-34 Pad

Location ID: 335439



Photo # 6367 Mechanical condition – possible wellhead leak on the LOUTHAN 31B-34 wellhead



Photo # 6368 Mechanical condition – possible wellhead leak on the LOUTHAN 31B-34 wellhead

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LOUTHAN 41B-34 Pad

Location ID: 335439



Photo # 6369 Mechanical condition – possible wellhead leak on the LOUTHAN 31B-34 wellhead



Photo # 6370 Mechanical condition – possible wellhead leak on the LOUTHAN 31B-34 wellhead

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LOUTHAN 41B-34 Pad

Location ID: 335439



Photo # 6371 Mechanical condition – possible wellhead leak on the LOUTHAN 31B-34 wellhead



Photo # 6372 Mechanical condition – possible wellhead leak on the LOUTHAN 31B-34 wellhead

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LOUTHAN 41B-34 Pad

Location ID: 335439



Photo # 6373 Mechanical condition – possible wellhead leak on the LOUTHAN 31B-34 wellhead



Photo # 6374 Mechanical condition – possible wellhead leak on the LOUTHAN 31B-34 wellhead

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LOUTHAN 41B-34 Pad

Location ID: 335439



Photo # 6375 Mechanical condition – possible wellhead leak on the LOUTHAN 31B-34 wellhead



Photo # 6376 Debris

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LOUTHAN 41B-34 Pad

Location ID: 335439



Photo # 6377 Debris



Photo # 6378 Debris