

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404098938

Date Received:  
02/19/2025

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

Heil, John

john.heil@state.co.us

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708905774

Inspection Date: 02/18/2025

FIR Submit Date: 02/18/2025

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

#### LOCATION - Location ID: 335439

Location Name: LOUTHAN-66S92W Number: 34NENE County: \_\_\_\_\_

Qtrqtr: NENE Sec: 34 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.490031 Longitude: -107.647012

#### FACILITY - API Number: 05-045- -00 Facility ID: 335439

Facility Name: LOUTHAN-66S92W Number: 34NENE

Qtrqtr: NENE Sec: 34 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.490031 Longitude: -107.647012

### CORRECTIVE ACTIONS:

1 CA# 202563

Corrective Action: All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition.

Date: 02/19/2025

Also remove and properly dispose of any stained materials

Response: CA COMPLETED

Date of Completion: 02/18/2025

Operator Comment: Production personnel responded to request from Wayne Smelser on same day of inspection and replaced a defective leaking o-ring in the lubricator cap. There was only minor soil staining at the base of the well. Impacted soils were cleaned up and properly disposed of. The total volume of fluids released is less than 1 bbl, and

therefore, this was not a reportable spill event. The leaking wellhead has been repaired. This corrective action is complete.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

--

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Production personnel responded to request from Wayne Smelser on same day of inspection and replaced a defective leaking o-ring in the lubricator cap. There was only minor soil staining at the base of the well. Impacted soils were cleaned up and properly disposed of. The total volume of fluids released is less than 1 bbl, and therefore, this was not a reportable spill event. The leaking wellhead has been repaired. This corrective action is complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 2/19/2025 8:55:21 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

--	--

Total Attach: 0 Files