

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404098938

Date Received:

02/19/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

Heil, John

john.heil@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 708905774

Inspection Date: 02/18/2025

FIR Submit Date: 02/18/2025

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335439

Location Name: LOUTHAN-66S92W Number: 34NENE County: _____

Qtrqtr: NENE Sec: 34 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.490031 Longitude: -107.647012

FACILITY - API Number: 05-045- -00 Facility ID: 335439

Facility Name: LOUTHAN-66S92W Number: 34NENE

Qtrqtr: NENE Sec: 34 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.490031 Longitude: -107.647012

CORRECTIVE ACTIONS:

1 CA# 202563

Corrective Action: All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition.

Date: 02/19/2025

Also remove and properly dispose of any stained materials

Response: CA COMPLETED

Date of Completion: 02/18/2025

Operator Comment: Production personnel responded to request from Wayne Smelser on same day of inspection and replaced a defective leaking o-ring in the lubricator cap. There was only minor soil staining at the base of the well. Impacted soils were cleaned up and properly disposed of. The total volume of fluids released is less than 1 bbl, and

therefore, this was not a reportable spill event. The leaking wellhead has been repaired. This corrective action is complete.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Production personnel responded to request from Wayne Smelser on same day of inspection and replaced a defective leaking o-ring in the lubricator cap. There was only minor soil staining at the base of the well. Impacted soils were cleaned up and properly disposed of. The total volume of fluids released is less than 1 bbl, and therefore, this was not a reportable spill event. The leaking wellhead has been repaired. This corrective action is complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental Lead

Date: 2/19/2025 8:55:21 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

404098938	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files