

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/13/2025

Submitted Date:

02/13/2025

Document Number:

708905741**FIELD INSPECTION FORM**Loc ID 336022 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**20 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284504	WELL	PR	09/01/2024	GW	045-12189	HANGS B1	PR
284505	WELL	PR	09/01/2024	GW	045-12190	HANGS B3	PR

General Comment:CECMC Inspection/Audit Report SummaryOn 02/13/2025 at approximately 11:21 hours, I, Compliance Specialist, Wayne SmelserConducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC HANGS B Pad.Location # 336022 in Garfield County Colorado.Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to Bald Eagle Roost Site.Location is in close proximity to Rule 411b Generalized External Buffer & Rule 411a Surface Water External Buffer.Location is approximately 36 yards from Last Chance Ditch.While there, I observed normal production operations.During this inspection/audit the following compliance issues were observed:1. Fencing - Barbed wire fence needs maintenance/wildlife hazard with a CA date of 02/14/20252. Tanks & Berms - Holes in secondary containment liner/liner needs maintenance with a CA date of 03/05/2025A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.This is a summary of inspection/audit report.Any corrective actions from previous inspections/audits that have not been addressed are still applicable.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911/970-285-9377		
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	Small amount of staining near tank battery & in secondary containment - please refer to photo log		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	LOCATION		
------	----------	--	--

Comment:	Barbed wire & wildlife fencing			
	Barbed wire fence needs maintenance in multiple areas - barbed wire laying on the ground in vegetated areas/wildlife hazard. At approximately 11:50 hours I called & spoke with Justin Mahaffey with TEP & let him know that the fencing needed maintenance & that the barbed wire on the ground in multiple areas constituted a wildlife hazard & that I was issuing a 24 hour corrective action on the observed compliance issue. At approximately 11:53 hours I called Mike Gardner with TEP & relayed the same information to him.			
Corrective Action:	Comply with CECMC wildlife rules		Date:	02/14/2025
Type	WELLHEAD			
Comment:	Cattle panels			
Corrective Action:			Date:	
Type	OTHER			
Comment:	Pig station - pipe rail fence			
Corrective Action:			Date:	
Equipment:				corrective date
Type: Deadman # & Marked	# 3			
Comment:	Marked			
Corrective Action:			Date:	
Type: Gas Meter Run	# 4			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 4			
Comment:				
Corrective Action:			Date:	
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:			Date:	
Type: Plunger Lift	# 2			
Comment:	Wells on plunger lift			
Corrective Action:			Date:	
Type: Bird Protectors	# 4			
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 2			
Comment:	Pressure transducers & Taylor plugs located on bradenheads, bradenhead valves are accessible.			
Corrective Action:			Date:	
Type: Pig Station	# 1			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment: Tank equipped with telemetry					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment: Centralized containment				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	HEATED STEEL AST		,
Comment: Tank equipped with telemetry					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Inadequate	Walls Insufficient		Inadequate
Comment: Multiple holes in secondary containment liner/liner needs maintenance Centralized containment				
Corrective Action: The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs.				Date: 03/05/2025

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	284504	Type:	WELL	API Number:	045-12189	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	284505	Type:	WELL	API Number:	045-12190	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse to none in areas
Compaction						Light compaction in some areas

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Fencing & Tanks & Berms for corrective actions & also refer to Housekeeping for comments.	smelserw	02/13/2025
Dead deer observed on location in the interim area - please refer to photo log		

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404093748	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6918593
708905742	Inspection/Audit 708905741 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6918591
708905743	Inspection/Audit 708905741 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6918592