

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403980311

Date Received:

02/20/2025

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708302854

Inspection Date: 10/03/2024

FIR Submit Date: 10/03/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 334812

Location Name: FEDERAL-67S96W Number: 3NESW County: \_\_\_\_\_

Qtrqtr: NESW Sec: 3 Twp: 7S Range: 96W Meridian: 6

Latitude: 39.465209 Longitude: -108.096636

### FACILITY - API Number: 05-045- -00 Facility ID: 334812

Facility Name: FEDERAL-67S96W Number: 3NESW

Qtrqtr: NESW Sec: 3 Twp: 7S Range: 96W Meridian: 6

Latitude: 39.465209 Longitude: -108.096636

### CORRECTIVE ACTIONS:

1 CA# 199297

Corrective Action: Secure equipment to comply with Rule 608.e.

Date: 10/10/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator  
Comment:

Separator lines have been plugged. Corrective Action complete.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 199298

Corrective Action: Install sign to comply with Rule 605.d.

Date: 11/02/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator  
Comment: Wellhead signs have been replaced. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

3 CA# 199299

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 10/18/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator  
Comment: Location and access road have been bladed/graded to repair rills and increase stabilization. Check dams have been maintained. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA #199297: Separator lines have been plugged. Corrective Action complete.  
CA #199298: Wellhead signs have been replaced. Corrective Action complete.  
CA #199299: Location and access road have been bladed/graded to repair rills and increase stabilization. Check dams have been maintained. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed:

Title: TEP Representative

Date: 2/20/2025 8:58:47 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403980311	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files