

Inspection/Audit Photos

Location: QB ENERGY HYRUP-68S96W/2NESW (PAD-2 K)

Location ID: 334342

Date: 02/18/2025




Photo # 5295 Location



Photo # 5274 Location



Inspection/Audit Photos

Location: QB ENERGY HYRUP-68S96W/2NESW (PAD-2 K)

Location ID: 334342

Date: 02/18/2025



Photo # 5281 Location



Photo # 5293 Location



Inspection/Audit Photos

Location: QB ENERGY HYRUP-68S96W/2NESW (PAD-2 K)

Location ID: 334342

Date: 02/18/2025



Photo # 5305 SW corner of location



Photo # 5306 NW corner of location

Inspection/Audit Photos

Location: QB ENERGY HYRUP-68S96W/2NESW (PAD-2 K)

Location ID: 334342

Date: 02/18/2025



Photo # 5307 NE corner of location



Photo # 5308 SE corner of location

Inspection/Audit Photos

Location: QB ENERGY HYRUP-68S96W/2NESW (PAD-2 K)

Location ID: 334342

Date: 02/18/2025



Photo # 5309 Lack of stabilization/compaction on location and lease road/insufficient tracking BMP's



Photo # 5310 Lack of stabilization/compaction on location and lease road/insufficient tracking BMP's

Inspection/Audit Photos

Location: QB ENERGY HYRUP-68S96W/2NESW (PAD-2 K)

Location ID: 334342

Date: 02/18/2025



Photo # 5311 Lack of stabilization/compaction on location and lease road/insufficient tracking BMP's



Photo # 5316 Lack of stabilization/compaction on location and lease road/tracking onto lease road/insufficient tracking BMP's