

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/26/2025

Submitted Date:

02/26/2025

Document Number:

713301785**FIELD INSPECTION FORM**Loc ID 417678 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|--------------|---------------|---------------------------------|
| , KPK | 303-825-4822 | cogcc@kpk.com | all inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 417676 | WELL | PR | 10/30/2013 | OW | 123-31718 | Noel 3-18 | PR |

General Comment:[well site inspection](#)

LocationOverall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | good | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|---------------------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | well head house with gate | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|-----------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 2 | | |
| Comment: | automation | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | pipd to surface | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 417676 Type: WELL API Number: 123-31718 Status: PR Insp. Status: PR

Producing Well

| | | | |
|--------------------|--|-------|--|
| Comment: | PR, Valves appeared to be open at time of inspection | | |
| Corrective Action: | | Date: | |

BradenHead

| | | | |
|-------------------------|------------------------------|------------------------|-----|
| Date of Last Brhd Test: | 10/30/2024 | Annual Brhd Completed? | Yes |
| Last Brhd Test Results | Initial Surf Csg Pressure: 0 | Fluid Type: | |
| | End Surf Csg Pressure: 0 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|---|---------|------------|
| Audit of scout card and related documents Routine inspection | kesterm | 02/26/2025 |
| This inspection does not nullify any orders or NOAV from the ECMC | | |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 713301786 | site pic | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6935614 |