

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/25/2025

Submitted Date:

03/03/2025

Document Number:

710500449

**FIELD INSPECTION FORM**

Loc ID 321614 Inspector Name: Sanchez, Chris On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 17180  
Name of Operator: CITATION OIL & GAS CORP  
Address: 14077 CUTTEN RD  
City: HOUSTON State: TX Zip: 77069

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	COGC
Costa, Ryan		ryan.costa@state.co.us	
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	COGC

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207522	WELL	TA	09/01/2020	OW	017-06457	RHOADES 13-35 1	EI
488413	SPILL OR RELEASE	CL	02/05/2025		-	RHOADES 13-35 #1	EI

**General Comment:**

This is an Environmental Inspection for the Rhoades 13-35 # 1, Spill Facility ID 488413

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	At the time of inspection, the well placard was not posted but was laying on the ground.		
Corrective Action:	Install sign to comply with Rule 605.d. Operator shall file an FIRR with attached photos showing the well placard secured in the ground	Date:	04/18/2025

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:


**Flaring:**

Type

Comment:

Corrective Action:

Date:


**Inspected Facilities**

Facility ID: 207522 Type: WELL API Number: 017-06457 Status: TA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 488413 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spill/Remediation:**

Comment: At the time of inspection there were no stained soils observed at the wellhead or former pump jack pad.  
Spill Facility ID 488413 closed with Analytical Data in Form 19 Document # 404062664

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500450	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6942536">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6942536</a>