

# Final Reclamation and Stormwater Inspection

January 27, 2025

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 305653

Well Name: WILLIAMS H. PELTIER #12-20

Inspection Document #: 718600336

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: WILLIAMS H. PELTIER #12-20  
Location ID: 305653



**Photo 1.** Looking northeast across location. Reclamation work has not begun on the pad.



**Photo 2.** Picture taken on eastern side of pad looking northeast across former wellbore. Excavations are filled.





Inspection Photos  
Location Name: WILLIAMS H. PELTIER #12-20  
Location ID: 305653



**Photo 3.** Looking north from wellbore. The area to the north, east and west of the pad appears to have reclamation work conducted.



**Photo 4.** Looking west from wellbore. A shed and riser remain on location (red circle).





Inspection Photos  
Location Name: WILLIAMS H. PELTIER #12-20  
Location ID: 305653



**Photo 5.** Looking east from wellbore. 5 abandoned locations are associated with this location, they do not appear to have been drilled.



**Photo 6.** Looking east from the edge of the pad. Stormwater BMPs (rock check dams) are present in this area. Corn/straw cover is present in this area. At the time of inspection no germination was observed and ground was primarily bare soil. Undesirable weeds Kochia and Russian thistle are present in the areas around the well pad.





Inspection Photos  
Location Name: WILLIAMS H. PELTIER #12-20  
Location ID: 305653



**Photo 7.** Photo taken to the north of the pad looking west. This area is outside the pad to the north. See Photo 6 comments.



**Photo 8.** Looking west across the north side of pad. A perimeter ditch with rock check dams is in place. Shed with pipe riser remains on location (red circle), also pictured in Photo 4.





Inspection Photos  
Location Name: WILLIAMS H. PELTIER #12-20  
Location ID: 305653



**Photo 9.** Looking west across the former tank battery in the center part of location. Check dams are present, dams are full of sediment.



**Photo 10.** Looking south across former tank battery. Erosion channels are present.

