

Inspection Photos

API: 009-06574

Operator: WEST TEXAS OPERATING
CO LLC DBA XTREME ENERGYCO

Inspection Date: 3/4/2025

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the offsite tank battery. The tank does not have sufficient secondary containment and the labels are missing.



Inspection Photos



Photo 2. The netting on the tank is not maintained to prevent wildlife entry.



Inspection Photos



Photo 3. The sign is partially buried in the sand and weeds are around the equipment..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:009-06574 | Date: 3/4/2025

Inspection Photos



Photo 4. Facing northwest toward the wellsite. The fence panels have fallen over around the pumpjack.

