

Inspection Photos

API: 009-06577

Operator: WEST TEXAS OPERATING
CO LLC DBA XTREME ENERGYCO

Inspection Date: 3/4/2025

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north toward the offsite tank battery. The tank does not have sufficient secondary containment.



Inspection Photos



Photo 2. The netting on the tank is not maintained to prevent wildlife entry.



Inspection Photos



Photo 3. The secondary containment is insufficient to contain a spill and there are weeds around the tank.



Inspection Photos



Photo 4. Facing northwest toward the wellsite.

