

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/04/2025

Submitted Date:

03/05/2025

Document Number:

713601933

FIELD INSPECTION FORMLoc ID 321151 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10560

Name of Operator: WEST TEXAS OPERATING CO LLC DBA XTREME

Address: PO BOX 2326

City: VICTORIA State: TX Zip: 77902

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
HAHN, MIKE		mhahn@xeogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206158	WELL	PR	07/01/2024	GW	009-06574	GODFREY 1-19	RI

General Comment:

This is a location inspection at the GODFREY #1-19 wellsite.
See attached photos and additional details within this report.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	The sign at the wellhead has fallen ove. The sign at the tank battery is partially burried and obscured by weeds.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	04/05/2025
Type	TANK LABELS/PLACARDS		
Comment:	The tank labels are missing.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	04/05/2025

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	The fence around the pumpjack has fallen over.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	03/12/2025

Equipment:

Type: Flow Line	#		corrective date
Comment:	It does not appear that the flowlines have been registered.		
Corrective Action:	It does not appear that the flowlines have been registered.		Date: 04/05/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1		Open Top		,	
Comment:	The netting on the open top tank is not maintained to prevent wildlife entry.					
Corrective Action:	Install or repair wildlife protection equipment. Comply with Rule 608.a.(13)				Date:	03/12/2025

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Inspector Name: COSTA, RYAN

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient		Inadequate	
Comment:	There is insufficient secondary containment to prevent a spill. The berm is wore down and degraded.				
Corrective Action:	Repair or install berms or other secondary containment devices.			Date:	04/05/2025

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601934	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6945598