

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/04/2025

Submitted Date:

03/05/2025

Document Number:

713601939

**FIELD INSPECTION FORM**Loc ID 320985 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10626

Name of Operator: DOVER ATWOOD CORPORATION

Address: 1875 HARSH AVENUE SE

City: MASSILLON State: OH Zip: 44646

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	
Kelly, George	(888) 858-7886	envexbaca@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205676	WELL	SI	08/01/2023	GW	009-06087	SCHREPEL, L 1-21	RI

**General Comment:**

This is a location inspection at the SCHREPEL, L #1-21 wellsite.  
See attached photos and additional details within this report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	The tank labels are missing.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	04/05/2025

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1		Open Top		,	
Comment:	The netting on the open top tank is not maintained to prevent wildlife entry.					
Corrective Action:	Install or repair wildlife protection equipment. Comply with Rule 608.a.(13)				Date:	03/12/2025

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		Inadequate
Comment:	There is insufficient secondary containment to prevent a spill. The berm is wore down and degraded.			
Corrective Action:	Repair or install berms or other secondary containment devices.			Date: 04/05/2025

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date: _____

**Flaring:**

Type		
Comment:		
Corrective Action:		Date: _____

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601940	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6945723">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6945723</a>