

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2025

Submitted Date:

03/06/2025

Document Number:

713301806

**FIELD INSPECTION FORM**Loc ID 318294 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	<a href="#">all inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241051	WELL	PR	07/01/2023	OW	123-08839	A L LUFT 2	PR

**General Comment:**[well site inspection](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	stained soil spots from well servicing equipment, photo 3&4		
Corrective Action:	Properly treat or dispose in accordance with Rule 905.f.		Date: 03/11/2025

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	piped to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	automation		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	natural gas		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>		
Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

**Inspected Facilities**

Facility ID: 241051 Type: WELL API Number: 123-08839 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 02/23/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment: submit report

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment

User

Date

Inspector Michael Kester, did audit scout card and related documents, conducted on-site inspection, Location: A L Loft 2  
 Operator: KPK  
 API#: 123-08839  
 County: Weld  
 While there, I observed well site with pumping unit  
 During this inspection the following possible compliance issues were observed:

kesterm

03/06/2025

Comply with Rule 905f, stained soil spots from well servicing equipment, corrective action date 3-11-2025 photos 3 & 4

Weather conditions: sunny and dry

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.

This inspection does not nullify any orders or NOAV from the ECMC

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713301807	site pic	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6947958">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6947958</a>