

Interim Reclamation and Stormwater Inspection

Date: 03/05/2025

Operator: CIVITAS NORTH LLC - 10661

Location ID: 454760

Inspection Document #: 718700165

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Grotheer 5-61 #11A
Location ID: 454760



Photo 1. Tumbleweed debris within well equipment.

Inspection Photos
Location Name: Grotheer 5-61 #11A
Location ID: 454760



Photo 2. Stained soil observed under separator.

Inspection Photos
Location Name: Grotheer 5-61 #11A
Location ID: 454760



Photo 3. Tumbleweed debris observed within equipment.

Inspection Photos
Location Name: Grotheer 5-61 #11A
Location ID: 454760



Photo 4. Southern interim areas appear to be progressing towards Rule 1003 with evidence of germination observed.

Inspection Photos
Location Name: Grotheer 5-61 #11A
Location ID: 454760



Photo 5. Russian thistle observed on edge of pad/interim areas.

Inspection Photos
Location Name: Grotheer 5-61 #11A
Location ID: 454760



Photo 6. Northern interim areas appear to be progressing towards Rule 1003 with evidence of germination observed.

Inspection Photos
Location Name: Grotheer 5-61 #11A
Location ID: 454760



Photo 7. Eastern interim areas appear to be progressing towards Rule 1003 with evidence of germination observed.