

# Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Esperanza/9-5 Pad

Location ID: 334510

Date: 03/3/2025



Photo # 6289 Entrance to location

Photo # 6300 Location

## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Esperanza/9-5 Pad

Location ID: 334510

Date: 03/3/2025



Mar 3, 2025 at 1:19:00 PM  
+39.208057,-107.894600 ±3.72m  
Collbran



Mar 3, 2025 at 1:21:01 PM  
+39.208034,-107.894569 ±7.07m  
Collbran

Photo # 6290 Location

Photo # 6293 Location

## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Esperanza/9-5 Pad

Location ID: 334510

Date: 03/3/2025



Photo # 6299 Location



Photo # 6306 SW corner of location

## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Esperanza/9-5 Pad

Location ID: 334510

Date: 03/3/2025



Photo # 6307 SE corner of location



Photo # 6308 NE corner of location

## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Esperanza/9-5 Pad

Location ID: 334510

Date: 03/3/2025



Photo # 6309 NW corner of location



Photo # 6310 Debris in the interim area - debris is interfering with interim reclamation & some of the debris also constitutes a wildlife hazard

## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Esperanza/9-5 Pad

Location ID: 334510

Date: 03/3/2025



**Photo # 6315 Debris in the interim area - debris is interfering with interim reclamation & some of the debris also constitutes a wildlife hazard**



**Photo # 6316 Debris in the interim area - debris is interfering with interim reclamation & some of the debris also constitutes a wildlife hazard**

## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Esperanza/9-5 Pad

Location ID: 334510

Date: 03/3/2025



Mar 3, 2025 at 1:38:42 PM  
+39.208393,-107.894459 ±5.76m  
Collbran



Mar 3, 2025 at 1:38:51 PM  
+39.208318,-107.894376 ±3.95m  
Collbran

**Photo # 6318 Debris in the interim area - debris is interfering with interim reclamation & some of the debris also constitutes a wildlife hazard**

**Photo # 6319 Debris in the interim area - debris is interfering with interim reclamation & some of the debris also constitutes a wildlife hazard**

## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Esperanza/9-5 Pad

Location ID: 334510

Date: 03/3/2025



**Photo # 6313 Debris in the interim area - debris is interfering with interim reclamation & some of the debris also constitutes a wildlife hazard**



**Photo # 6323 Debris**