

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/03/2025

Submitted Date:

03/06/2025

Document Number:

707603719

FIELD INSPECTION FORMLoc ID 445094 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------------------------------|
| , | | rbucogccinspectionreports@c hevron.onmicrosoft.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 445095 | WELL | PR | 03/01/2022 | OW | 123-42882 | Shadow A26-646 | PR |
| 445097 | WELL | PR | 07/01/2020 | OW | 123-42884 | Shadow A26-637 | PR |
| 445101 | WELL | PR | 07/01/2020 | OW | 123-42887 | Shadow A26-632 | PR |

General Comment:

This is a WELL inspection.
Well(s): 3: Producing | PR.
Battery: Active.

Centralized Battery serves 4 Location IDs
(445098, 445094, 445106, 445163).
(Well(s): 13: Producing | PR).

Centralized Battery serves 1 Tank Battery Facility ID
(480908).

Reference:

- A.) Field Inspection Report doc. #707603717 and/or Location ID #445098 for PR Well(s) info.
- B.) Field Inspection Report doc. #707603719 and/or Location ID #445094 for PR info.
- C.) Field Inspection Report doc. #707603721 and/or Location ID #445106 for PR Well(s) info.
- D.) Field Inspection Report doc. #707603723 and/or Location ID #445163 for PR Well(s) info.
- E.) Field Inspection Report doc. #707603725 and/or Facility ID #480908 for Battery / Facility, Equipment info.

Location**Lease Road:**

| | | | |
|-------------------|----------|-------|--|
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action | L | Date: | |

Overall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|----------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Wellsite(s): 3 | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | |
| Corrective Action: | | Date: _____ |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-------------------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Wellsite(s): 3 Iron panel. | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|---------------------------|---|-------|-----------------|
| | | | corrective date |
| Type: Ancillary equipment | # 0 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 3 | | |
| Comment: | Wellsite(s): 3 | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 3 | | |
| Comment: | Wellsite(s): 3 Appears plumbed to surface. | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------|---|----------|---------------------|---------|-----------------------|
| | | | CENTRALIZED BATTERY | | 40.460012,-104.477758 |

| | | |
|--------------------|--|-------|
| Comment: | Centralized Battery serves 4 Location IDs (445098, 445094, 445106, 445163). (Well(s): 13: Producing PR). Centralized Battery serves 1 Tank Battery Facility ID (480908). | |
| Corrective Action: | | Date: |

Paint

| | | |
|------------------|--|--|
| Condition | | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|--|--------|----------------------------|------|------------------------|-----------|-------------|----|---------------|----|
| Facility ID: | 445095 | Type: | WELL | API Number: | 123-42882 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | Producing PR. | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: | | 01/16/2025 | | Annual Brhd Completed? | | Yes | | | |
| Last Brhd Test Results | | Initial Surf Csg Pressure: | | 0 | | Fluid Type: | | | |
| | | End Surf Csg Pressure: | | 0 | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 445097 | Type: | WELL | API Number: | 123-42884 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | Producing PR. | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: | | 04/08/2024 | | Annual Brhd Completed? | | Yes | | | |
| Last Brhd Test Results | | Initial Surf Csg Pressure: | | 0 | | Fluid Type: | | | |
| | | End Surf Csg Pressure: | | 0 | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 445101 | Type: | WELL | API Number: | 123-42887 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | Producing PR. | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: | | 06/27/2024 | | Annual Brhd Completed? | | Yes | | | |
| Last Brhd Test Results | | Initial Surf Csg Pressure: | | 22 | | Fluid Type: | | | |
| | | End Surf Csg Pressure: | | 0 | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

| Comment | User | Date |
|---|--------|------------|
| <p>CECMC Inspection Report Synopsis:</p> <p>On MON 03/03/2025 at approximately 14:14 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: Shadow/A26-651 Pad Location ID: 445094 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Mostly Cloudy, dry.</p> <p>While there, I observed: Well(s): 3: Producing PR. Battery: Active.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p> | evinsb | 03/06/2025 |

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------|---|
| 707603720 | Site photo(s) | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6949100 |