

Inspection/Audit Photos
Location Name: QB Energy BJM 31-6C (H36NW) Pad
Location ID: 334966



Photo # 1717 From entrance to location



Photo # 1718 Location

Inspection/Audit Photos
Location Name: QB Energy BJM 31-6C (H36NW) Pad
Location ID: 334966



Photo # 1719 Location



Photo # 1720 Location

Inspection/Audit Photos
Location Name: QB Energy BJM 31-6C (H36NW) Pad
Location ID: 334966



Photo # 1721 Location



Photo # 1722 Location

Inspection/Audit Photos
Location Name: QB Energy BJM 31-6C (H36NW) Pad
Location ID: 334966



Photo # 1723 PRV vent line does not comply with CECMC rules



Photo # 1724 PRV vent line does not comply with CECMC rules