

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/04/2025

Submitted Date:

03/06/2025

Document Number:

707801453

**FIELD INSPECTION FORM**Loc ID 334649 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

17 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, QB		ecmc.inspections@qb-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265640	WELL	PR	10/19/2003	GW	045-09042	GMR 4-16D (M3A)	PR
265641	WELL	PR	10/17/2003	GW	045-09043	GMR 3-11B (M3A)	PR
265642	WELL	PR	11/01/2024	GW	045-09044	GMR 9-1D (M3A)	PR
265643	WELL	PR	10/15/2003	GW	045-09045	GMR 4-9D (M3A)	PR
265645	WELL	PR	09/08/2003	GW	045-09046	GMR 3-13D (M3A)	PR
265646	WELL	PR	10/10/2003	GW	045-09047	GMR 3-13A (M3A)	PR
265647	WELL	PR	08/28/2003	GW	045-09048	GMR 3-13B (M3A)	PR
266010	WELL	PR	09/10/2003	GW	045-09051	HMU 3-14D (M3A)	PR
266011	WELL	PR	09/05/2003	GW	045-09049	HMU 10-3B (M3A)	PR
266012	WELL	PR	10/13/2003	GW	045-09050	HMU 3-14B (M3A)	PR
273556	WELL	PR	11/26/2005	GW	045-10260	GMR 3-12D (M3A)	PR
273557	WELL	PR	12/01/2005	GW	045-10261	GMR 3-13C (M3A)	PR

**General Comment:**

ECMC Inspection Report Summary

On Tuesday 3/4/2025, I, Inspector Scott Ramsey, conducted a routine inspection/audit at Caerus M3A, at Location # 334649 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Location shows signs if lack of stabilization/ compaction

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911/970-285-2615

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Emission Control Device	# 1		
Comment:	Metered		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 12		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 12		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	265640	Type:	WELL	API Number: 045-09042 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	265641	Type:	WELL	API Number: 045-09043 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	265642	Type:	WELL	API Number: 045-09044 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	265643	Type:	WELL	API Number: 045-09045 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	265645	Type:	WELL	API Number: 045-09046 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	265646	Type:	WELL	API Number: 045-09047 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	265647	Type:	WELL	API Number: 045-09048 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	266010	Type:	WELL	API Number: 045-09051 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	266011	Type:	WELL
API Number:	045-09049	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	266012	Type:	WELL
API Number:	045-09050	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	273556	Type:	WELL
API Number:	045-10260	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	273557	Type:	WELL
API Number:	045-10261	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Compaction						
Berms						

Comment: 1. Location shows signs if lack of stabilization/ compaction. Maintenance relative to storm water runoff, operators shall consider seasonal factors, such as winter snow cover and spring runoff from snowmelt, to ensure site conditions and controls are adequate and in place to effectively manage storm water. Places with sparse to no gravel & light compaction are present on location. Sparse to no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action: Install, maintain or repair required BMPs in order to achieve stabilization on location

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404119073	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6948498">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6948498</a>
707801459	Photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6948480">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6948480</a>