

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2025

Submitted Date:

03/06/2025

Document Number:

701104153**FIELD INSPECTION FORM**Loc ID 458475 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name       | Phone | Email                          | Comment |
|--------------------|-------|--------------------------------|---------|
| ,                  |       | ecmc.inspections@qb-energy.com |         |
| Schlagenhauf, Mark |       | mark.schlagenhauf@state.co.us  |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name          | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 458469      | WELL | PR     | 07/28/2020  | GW         | 045-24174 | ELU A24 Fed 15D-13-496 | EG          |

**General Comment:**

Flowline Integrity Inspection

Form 19 Spill/Release Report (Supplemental) [#404105253]

"Elbow and approximately 15' of flowline replaced with new upgraded material. Additional line exposed for inspection of integrity."

Description of root cause of failure not given in report.

"A 90 degree elbow on the flowline was discovered with a small pinhole."

Provide details of root cause of the pinhole. By 3/14/25

