

Construction and Stormwater Inspection

March 17, 2025

Operator: BISON IV OPERATING LLC - 10670

Location ID: 486770

Inspection Document #: 718800046

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Triggerfish
Location ID: 486770



Photo 1. Photo taken from the southern perimeter of the site, near the location's entrance from the access road, facing East. Photo illustrates that the Operator has installed a ditch BMP.



Photo 2. Photo taken from the southern perimeter of the site, facing West. Photo illustrates that a temporary BMP has been installed along the perimeter of the site.

Inspection Photos
Location Name: Triggerfish
Location ID: 486770



Photo 3. Photo taken from the southeastern perimeter of the site, facing East. See comments under photo 2.

Note: Wattles have been overlapped per good engineering practices.



Photo 4. Photo taken from the northeastern portion of the location, facing Southwest. Photo illustrates Operator is in the process of topsoil salvage.

Note: At the time of this inspection, major construction activities were not occurring.



Inspection Photos
Location Name: Triggerfish
Location ID: 486770



Photo 5. Photo taken from the northeastern portion of the working pad, facing southwest. Photo illustrates a portion of the topsoil stockpile.



Photo 6. Photo taken from the east perimeter of the location, facing Northwest. See comments under Photo 4.



Inspection Photos
Location Name: Triggerfish
Location ID: 486770



Photo 7. Photo taken from the western perimeter of the site, facing East. See comments under Photo 2.



Photo 8. Photo taken from northwestern portion of the site, facing Southeast. Photo illustrates that the operator has marked the topsoil stockpile location.

Inspection Photos
Location Name: Triggerfish
Location ID: 486770



Photo 9. Photo taken along a portion of the western access road. Photo illustrates Operator is using access road topsoil as fill material and there are no access road BMPs.



Photo 10. Photo taken from the previous photo location, along the access road, facing East. The photo illustrates vegetation and topsoil being used as fill material to construct the access road.



Inspection Photos
Location Name: Triggerfish
Location ID: 486770



Photo 11. Photo taken from the western portion of the access road. Photo illustrates the Operator has only grubbed the access road and has not salvaged topsoil.



Photo 12. Photo taken from the access road. See comments under photo 11.