

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404133013

Date Received:

03/19/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Noble, Legacy

rbucogccinspectionreports@chevron.onmicrosoft.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 710100354

Inspection Date: 03/06/2025

FIR Submit Date: 03/10/2025

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 421031

Location Name: DECHANT Number: 3-19HZ County: _____

Qtrqtr: SWS Sec: 19 Twp: 2N Range: 64W Meridian: 6
W

Latitude: 40.117717 Longitude: -104.601552

FACILITY - API Number: 05-123- -00 Facility ID: 421031

Facility Name: DECHANT Number: 3-19HZ

Qtrqtr: SWS Sec: 19 Twp: 2N Range: 64W Meridian: 6
W

Latitude: 40.117717 Longitude: -104.601552

CORRECTIVE ACTIONS:

1 CA# 203128

Corrective Action: Inspect, maintain and repair tanks to comply with Rule 609.b.

Date: 04/09/2025

Response: CA COMPLETED

Date of Completion: 03/18/2025

Operator Comment: Tanks were inspected and found to be in operational condition. No pitting or corrosion. The only producing well into this tank is Shut In and has yet to be determined if it will be put back into production. If the well is put back into production the tank will be repainted.

ECMC Decision: _____

Date: 3/19/2025 8:36:47 PM

Page 2 of 2