

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/13/2025

Submitted Date:

03/20/2025

Document Number:

698603324

**FIELD INSPECTION FORM**Loc ID 337354 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

16 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285231	WELL	PR	06/19/2006	GW	125-10095	D & S 22-31 4N46W	PR

**General Comment:**

Routine Inspection.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained County Road.		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Lease sign posted at remote Gas Meter Run.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign at wellhead location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency contact information posted on Lease sign.

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Stock panel fencing around surface equipment at remote gas metering location.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well location.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Pump Jack Power and Control Panel.		
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located on CR 49 & CR P at shared gathering location. Digital Gas Meter Run. Meter Calibration/Test Log dated 3-3-23. Well Inlet Valve open. Gas Outlet Valve open. Meter not calibrated annually.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date: 04/20/2025
Type: Dehydrator	# 1		
Comment:	Dehydrator (Drip Bottle) on gas meter run inlet.		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric Motor.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve closed. Casing valve open.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Shared Remote Gas Meter Shed.		
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	285231	Type:	WELL	API Number:	125-10095	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Rods and tubing in wellbore. Tubing valve closed. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.  Electronic Well File reflects last Production/Status reported 1/1/2025 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.								
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698603355	Inspection photos.	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6968573">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6968573</a>