

Inspection Photos

API: 071-07311

Operator: WAPITI OPERATING LLC

Inspection Date: 3/20/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-07311 | Date: 3/20/2025

Inspection Photos



Photo 2. There is stained soil at this flowline valve that needs to be cleaned up.



Inspection Photos



Photo 3. Well sign is posted by the meter shed.



Inspection Photos



Photo 4. There is wet stained soil at the wellhead from a PW leak that needs to be cleaned up. Ensure leak is controlled.



Inspection Photos



Photo 5. Facing west along the fill slope which is stabilized with vegetation.

