

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2025

Submitted Date:

03/21/2025

Document Number:

710100373**FIELD INSPECTION FORM**Loc ID 464095 Inspector Name: Anderson, Laurel On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
Kiel, Macy	970-515-1110	Macy_Kiel@oxy.com	Staff Environmental Engineer

General Comment:

ECMC Environmental Inspection of the following Kerr McGee/Oxy (Operator) facilities:
 Paragon X30-12 & 14 Tank Battery
 Facility ID 489511
 Location ID 464095

Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no Operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Current site status:

- Minor weeds/debris/trash
- Inadequate secondary containment berms (burrows)/southern sidewall appears to have been removed.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Inadequate secondary containment. Animal burrows and weeds were observed in/around the horizontal separator and produced water vessel/crude oil AST earthen secondary containment berms. Southern wall of the horizontal separator's earthen secondary containment berm appears to have been removed (See Photos).			
Corrective Action:	Comply with Rules 902.a., 902.b. and 902.c. Operators shall maintain earthen secondary containment berms to prevent pollution, adverse environmental impacts and the potential for unauthorized discharge of oil, condensate, gas, and/or other E&P Waste.			Date: 04/04/2025

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710100374	2025_0306_ Paragon x30-12 & 15_Photo Documentation	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6969559