

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/24/2025

Submitted Date:

03/25/2025

Document Number:

707801497

FIELD INSPECTION FORM

Loc ID 416979	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 24 Number of Comments 6 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: ECMC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: 1058 COUNTY ROAD 215 City: PARACHUTE State: CO Zip: 81635				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416984	WELL	PR	03/22/2011	GW	045-19420	GGU MILLER FED 34B-32-691	PR
416985	WELL	PR	05/05/2011	GW	045-19421	GGU MILLER FED 33B-32-691	PR
416987	WELL	PR	03/22/2011	GW	045-19422	GGU MILLER FED 33A-32-691	PR
416988	WELL	PR	05/10/2011	GW	045-19423	GGU MILLER FED 33C-32-691	PR
416989	WELL	PR	05/10/2011	GW	045-19424	GGU MILLER 23B-32-691	PR
416990	WELL	PR	04/15/2011	GW	045-19425	GGU MILLER 24B-32-691	PR
416991	WELL	PR	04/15/2011	GW	045-19426	GGU MILLER 24A-32-691	PR
416992	WELL	PR	03/19/2015	GW	045-19427	GGU MILLER 24D-32-691	PR
416993	WELL	PR	03/23/2011	GW	045-19428	GGU MILLER FED 34C-32-691	PR
416994	WELL	PR	05/05/2011	GW	045-19429	GGU MILLER 24C-32-691	PR
416995	WELL	PR	05/05/2011	GW	045-19430	GGU MILLER 23C-32-691	PR
416996	WELL	PR	03/22/2011	GW	045-19431	GGU MILLER FED 34D-32-691	PR
416997	WELL	PR	03/22/2011	GW	045-19432	GGU MILLER FED 34A-32-691	PR

General Comment:

CECMC Inspection Report Summary

On Monday 3/24/2025, I, Inspector Scott Ramsey, conducted a routine inspection/audit at TEP GGU Miller MDP 6, at Location # 416979 in Garfield county Colorado. Shaun Kellerby was also on the inspections/audits with myself.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad. No evidence of a tracking pad on location.

We were escorted by lead pumper through locked gate and he also followed us around locations.

During this inspection the following compliance issues were observed:

1. Access road rock check dams are in need maintained.
2. Chemical tank containment is leaking, possibly chemical staining because pumps for chemical are also leaking. Stained soils around chemical containment.
3. Unused poly piping around location.
4. Random debris (B/H caps)
5. Open rat hole
6. Some tank labels are illegible.

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Some tank labels are illegible.		
Corrective Action:	Provide proper labeling	Date:	04/25/2025
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of fluid. Labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Chemical tank containment is leaking, possibly chemical staining because pumps for chemical are also leaking. Stained soils around chemical containment.		
Corrective Action:	Repair or replace secondary containment and Contact environmental for remediation of soils.	Date:	03/27/2025
Type	OTHER		
Comment:	Open rat hole at well head.		
Corrective Action:	Eliminate possibility of wildlife or personnel from falling into open holes.	Date:	04/04/2025
Type	DEBRIS		
Comment:	Random debris (B/H caps)		
Corrective Action:	Remove debris	Date:	04/04/2025
Type	STORAGE OF SUPL		
Comment:	Unused poly piping around location.		
Corrective Action:	Remove poly piping	Date:	05/02/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 13		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 13		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	Not metered		
Corrective Action:		Date:	
Type: Bird Protectors	# 15		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 13		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	8	500 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date: <div></div>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date: <div></div>

Flaring:

Type			
Comment:			
Corrective Action:			Date: <div></div>

Inspected Facilities				
Facility ID:	416984	Type:	WELL	API Number: 045-19420 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	416985	Type:	WELL	API Number: 045-19421 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	416987	Type:	WELL	API Number: 045-19422 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	416988	Type:	WELL	API Number: 045-19423 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	416989	Type:	WELL	API Number: 045-19424 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	416990	Type:	WELL	API Number: 045-19425 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	416991	Type:	WELL	API Number: 045-19426 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	416992	Type:	WELL	API Number: 045-19427 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	416993	Type:	WELL
API Number:	045-19428	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	416994	Type:	WELL
API Number:	045-19429	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	416995	Type:	WELL
API Number:	045-19430	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	416996	Type:	WELL
API Number:	045-19431	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	416997	Type:	WELL
API Number:	045-19432	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Ditches						
		Check Dams				
Ditches						
Berms						

Comment: 1. Access road rock check dams are in need maintained.

Corrective Action: Install, maintain or repair required BMPs

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	430352	400278587	
	451892	401224814	

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801502	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6974098