

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Hayward/0993-25-09 Pad

Location ID: 455725

Date: 03/24/2025



Photo # 6681 Entrance to location/Lack of stabilization/compaction/insufficient tracking BMP's



Photo # 6680 Location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Hayward/0993-25-09 Pad

Location ID: 455725

Date: 03/24/2025



Photo # 6683 Lack of stabilization/compaction on location/insufficient tracking BMP's



Photo # 6687 Lack of stabilization/compaction on location/insufficient tracking BMP's

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Hayward/0993-25-09 Pad

Location ID: 455725

Date: 03/24/2025



Photo # 6688 Lack of stabilization/compaction on location/insufficient tracking BMP's



Photo # 6707 Lack of stabilization/compaction on location/insufficient tracking BMP's

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Hayward/0993-25-09 Pad

Location ID: 455725

Date: 03/24/2025



Photo # 6710 Lack of stabilization/compaction on location/insufficient tracking BMP's



Photo # 6698 Stockpiled soils on location with no BMP's

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Hayward/0993-25-09 Pad

Location ID: 455725

Date: 03/24/2025



Photo # 6699 Stockpiled soils on location with no BMP's



Photo # 6712 Stockpiled soils on location with no BMP's

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Hayward/0993-25-09 Pad

Location ID: 455725

Date: 03/24/2025



Photo # 6738 Unknown fluid around frac tanks



Photo # 6739 Unknown fluid around frac tanks

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Hayward/0993-25-09 Pad

Location ID: 455725

Date: 03/24/2025



Photo # 6742 Unknown fluid around frac tanks



Photo # 6745 Unknown fluid around frac tanks

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Hayward/0993-25-09 Pad

Location ID: 455725

Date: 03/24/2025



Photo # 6746 Unknown fluid around frac tanks



Photo # 6747 Unknown fluid around frac tanks

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Hayward/0993-25-09 Pad

Location ID: 455725

Date: 03/24/2025



Photo # 6757 Staining on location



Photo # 6759 Staining on location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Hayward/0993-25-09 Pad

Location ID: 455725

Date: 03/24/2025



Photo # 6766 Vehicle tracking onto lease road/Insufficient tracking BMP's



Photo # 6767 Vehicle tracking onto lease road/Insufficient tracking BMP's

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Hayward/0993-25-09 Pad

Location ID: 455725

Date: 03/24/2025



Photo # 6700 Dumpster open & available for entry by wildlife/wildlife hazard



Photo # 6709 Dumpster open & available for entry by wildlife/wildlife hazard

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Hayward/0993-25-09 Pad

Location ID: 455725

Date: 03/24/2025



Photo # 6768 Debris



Photo # 6769 Debris

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Hayward/0993-25-09 Pad

Location ID: 455725

Date: 03/24/2025



Photo # 6770 Debris

